

**BellSouth Corporation**  
Suite 900  
1133-21st Street, N.W.  
Washington, D.C. 20036-3351

mary.henze@bellsouth.com

Mary **L. Henze**  
Executive Director  
Federal Regulatory Affairs

202 463 4109  
Fax 202 463 4631

September 30, 2002

**RECEIVED**

SEP 30 2002

FEDERAL COMMUNICATIONS COMMISSION  
OFFICE OF THE SECRETARY

Ms. Marlene H. Dortch  
Secretary  
Federal Communications Commission  
445 Twelfth Street, S.W.  
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98


Dear Ms. Dortch:

Number	Type of Change Planned	Location of Change
91083336	Fiber replacing copper	Pensacola, FL
91083337	Fiber replacing copper	Greensboro, NC

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of the notice is also available at: <http://www.interconnection.bellsouth.com/notifications/network/index.html>

Should you have any questions, please contact me at (202) 463-4109.

Sincerely,



Mary L. Henze  
Executive Director - Federal Regulatory

Attachments

cc: Michelle Carey (with diskette)

Carmell Weathers (with diskette)

**Notice of Network Change - Pensacola, Florida**  
Replace Copper Facilities with Fiber Optic and Digital Loop Carrier Systems

**Carrier**

BellSouth Telecommunications, Inc  
675 West Peachtree Street NE  
Atlanta, Georgia 30375

**Date Changes are to Occur:** Complete Cutover June 1, 2003

**Location of Changes:** Pensacola, Florida - Carrier Serving Area 1164A - Distribution Areas served by cable 1804 in the vicinity of Cross Street and 9<sup>th</sup> Avenue.

**Description of Change Planned:** Copper feeder facilities will be replaced with Fiber Optic and Digital Loop Carrier systems.

**Description of Reasonably Foreseeable Impact of the Planned Change:** After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carriers to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

<b>Contact:</b> <u>Technical questions</u> relating to this change should be directed to:	Brad Huggins, Loop Capacity Manager 605 W Garden St Pensacola, Florida 32501 (850) 436-1671
---	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or  
780-2171 (FL, GA, NC, SC)  
(If you are calling from a mandatory 10-digit calling area,  
include your local area code.)

Outside BellSouth region: 1-800-786-7619  
Fax: 1-205-321-2191

Notice of Network Change – Greensboro, North Carolina  
Replace Copper Facilities with Fiber Optic and Digital Loop Carrier System  
Due to Piedmont Triad Airport Authority Runway Addition

Carrier  
BellSouth Telecommunications, Inc.  
675 West Peachtree Street NE  
Atlanta, Georgia 30375

Date Changes are to Occur: Beginning April 1, 2003 and complete September 30, 2003

Location of Changes: Greensboro, North Carolina - North Regional Road, North of the Bryan Boulevard (existing) and associated crossconnect boxes at Ped 1 Airport Center Drive, R 7615 Business Park Drive, and P 46 North Regional Road including all terminals serving from these connect points, feeding Pleasant Ridge Road, Highway 68 (North of Pleasant Ridge), Business Park Drive, Airport Center Drive, and Cude Road

Description of Change Planned: Copper feeder facilities will be replaced with Fiber Optic and Digital Loop Carrier systems due to runway additions and associated roadwork initiated by the Piedmont Triad Airport Authority.

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits working on unbundled copper loops in this area will need to be moved off the copper cables by April 2003. Requests for new copper loops in this area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL), or line-sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u>	Warren Harris
relating to this change	Rm 202, 2200 Pinecroft Rd
should be directed to:	Greensboro, NC 27407
	336-855-4768

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In <b>the</b> BellSouth region:	557-2647 (AL, KY, LA, <b>MS ,TN</b> ) or 780-2171 (FL, <b>GA, NC .SC</b> ) (If you are calling from a mandatory 10-digit calling area, include your local area code.)
Outside BellSouth region:	1-800-786-7619
Fax:	1-205-321-2191

Notice of Network Change Under Rule 51.329(a)  
Notification No. SN91083337  
Issue Date: September 30, 2002